

General Environmental Incident Summary

Incident: 2023 **Date/Time Notice:** 8/21/2013 1530 **DEM Incident No:**
Responsible Party: Bakken Oil Express LLC Rail Hub
Date Incident: 8/21/2013 **Time Incident:** 02:20 **Duration:** 15 minutes
County: Stark **Twp:** 139 **Rng:** 97 **Sec:** 11 **Qtr:**
Lat: 46.86897 **Long:** -102.88370 **Method:** Derived from TRS
Location Description: 3761 115th Ave. SW. Dickinson, ND 58601

Submitted By: Chris Lewis **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Chris Lewis
3761 115th Ave. SW
Dickinson, ND 58601

Distance Nearest Occupied Building:

Type of Incident: Tank Overflow

Description of Released Contaminant: 1267 Crude Oil

Volume Spilled: 60.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Yes

Cause of Incident:

Tank Overflow of 105,000 BBL above ground storage tank

Risk Evaluation:

High LEL atmosphere. Tank was purged with CO2 gas to eliminate risk.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil.

Action Taken or Planned:

Spill was contained in tank containment. MBI vac trucked removed pooled oil to Knutdson. Steir Oil Field Services will be excavating soil.

Wastes Disposal Location: Steir Oil field Services will take it to Indian Hills.

Agencies Involved:

Updates

Date: 8/21/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Transfer facility. NDDoH jurisdiction. Followup is necessary. Call for appointment.

Date: 8/22/2013 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

The temp was 65 °F, with a wind from the southeast 10-15 miles per hour. Talked to company representative at the site. They will be washing the tank down and collecting the oil and water. The cleanup crew was at the site. The stained soil will be removed and stockpiled on clay and covered with plastic until it can be hauled away. Test will be conducted on soil to be hauled and the excavation area. A follow-up inspection will be done to check the progress of the cleanup.

Date: 12/12/2013 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

The temperature was 26 °F with a wind from the southeast at eight miles per hour. I went to the Bakken Express site along highway 10, located west of Dickinson. The oil soaked soil was hauled out and the area around the tank was redone. Everything was looking good. No further follow-up is needed at this time.